| Series | Fault | Reason | Possible cause | Remedies |
|--|--|---|--|--|
| MKS/MKRS, MCPS, LKPS, LBPS, MBPS, UBPS, KBHS, LBHS, RBPS,TPS, DKPS, DKHS, LCPS | | Operating pressure is absent | Operating pressure is set too low | Set the min. operating pressure according to the "Technical data" table |
| | | | Leaking, clogging, pinching of the line or power supply failure | Check the pressure supply |
| | | | Operating pressure is insufficient | Increase the operating pressure or use an element with reduced opening pressure (3 or 4 bar version), otherwise contact Zimmer GmbH Service |
| MK/MKR, MCP, LKP, | Element does not close / | Operating pressure is absent | Operating pressure is set too low | Set the operating pressure according to the "Technical data" table |
| KWH, KBH, LCP | holding force is not achieved | Operating pressure is absent | Leaking, clogging, pinching of the line or power supply failure | Check the pressure supply, connections and lines and replace them if necessary |
| MKS/MKRS, MCP, MCPS, LKP, LKPS, LBPS, MBPS, UBPS, RBPS, TPS, DKPS,LCP,LCPS | Response time is too long / element opens after a delay | Insufficient air supply | Valve is too small | Choose a valve with a larger flow rate |
| | | | Line between valve and element is too long | Select the shortest possible lines between valve and element |
| | | Too little exhaust air | Quick exhaust valve / air filter covered | Make sure the opening on the quick exhaust valve / air filter is open; if necessary, change the air filter to the opposite side. |
| | | | Quick exhaust valve / air filter clogged | Replace the air filter / remove contamination |
| | | | Line between valve and element is too long | Make the line between the valve and element as short as possible |
| KWH, KBH, KBHS, LBHS, DKHS | Response time is too long / element opens after a delay | Insufficient oil supply | Valve is too small | Choose a valve with a larger flow rate |
| | | | Line between valve and element is too long | Select the shortest possible lines between valve and element |
| | | Not enough oil displacement | Line between valve and element is too long | Select the shortest possible lines between valve and element |
| MKS/MKRS, MCP, MCPS, LKP, LKPS, LBPS, MBPS, UBPS, RBPS, TPS, DKPS, LCP, LCPS | Leaking, and/or blow-off noise can be heard | Housing parts are leaky | Seals are not properly applied | Open and close the element at least 20 times within 5 seconds |
| | | Connections are leaky | | Check the pneumatic connections and lines and replace them if necessary |
| | | Wear | Element has reached the end of its service life | Replace element |
| KWH, KBH, KBHS, LBHS, DKHS | Leakage / oil loss | Housing parts are leaky | Seals are not properly applied | Open and close the element at least 20 times within 5 seconds |
| | | Connections are leaky | Loose connections, defective lines | Check the hydraulic connections and lines and replace them if necessary |
| | | Wear | Element has reached the end of its service life | Replace element |
| HK/miniHK/HKR, MK/MKR, MKS/MKRS, MCP, MCPS, LKP, LKPS, KWH, LCE, LCP, LCPS, LKE | | Element does not match the profile rail / round guide rail | Dimensional tolerance between contact profile and profile rail / round guide divergent | Under "Selection guide" on the website, check whether the element matches the rail, otherwise contact Zimmer GmbH Service |
| | | | Mounting piece is not rigid enough | Installation surface should be completely covered and be sufficiently rigid (approx. thickness of the rear of the element) |
| | | Element does not withstand bending | Mounting screws loose or of the wrong strength class | Observe the information in the "Technical data" table |
| LBPS, MBPS, UBPS, KBH, KBHS, LBHS, RBPS | Insufficient holding force / holding torque | Element does not match the profile rail / round guide rail | Dimensional tolerance between contact profile and profile rail / round guide divergent | Under "Selection guide" on the website, check whether the element matches the rail, otherwise contact Zimmer GmbH Service |
| | | Element does not withstand bending | Mounting piece is not rigid enough | Installation surface should be completely covered and be sufficiently rigid (approx. thickness of the rear of the element) |
| | | | Mounting screws loose or of the wrong strength class | Observe the information in the "Technical data" table |
| | | Brake lining is worn | Max. dynamic brake cycles reached | Replace the element; the brake lining cannot be replaced because of tolerances |
| TPS, DKPS, DKHS | Holding torque is insufficient | Shaft tolerance not maintained | Shaft tolerance not maintained | Zimmer GmbH Service |
| | | Element does not withstand bending | Element does not withstand bending | Installation surface should be completely covered and be sufficiently rigid (approx. thickness of the rear of the element) |
| | | | | |
| | | | Concentricity error | Observe the information in the "Technical data" table |
| | | Concentricity error | Installation surfaces of the shaft and element do not correspond to the specifications | Dismantle the element and pull it off of the shaft, rework the surfaces to match the specifications, otherwise contact Zimmer GmbH Service |
| | | | Element was not clamped when the screws were installed | Loosen the attachment screws and install them in accordance with the assembly instructions |
| MBPS, UBPS, RBPS | Displacement resistance is too high | Brake pads are touching the profile rail / round guide | Dimensional tolerance between contact profile and profile rail / round guide divergent | Check the dimensional tolerance of the guide rail, otherwise contact Zimmer GmbH Service |
| | | | Element is misaligned | Loosen the attachment screws and reinstall them in accordance with the installation instructions |
| | | Wiper resistance increased | Poor lubrication conditions, resistance increased as a result of wiper pretension | The displacement resistance can be up to 100 N, depending on the wiper. If it is greater than that, contact Zimmer GmbH Service |
| LKE, LCE | Output status "Error" (Overcurrent) | Max. motor current exceeded | Dimensional tolerance between contact profile and profile rail deviates | Via "Selection guide" on the website, check whether the element matches the rail, otherwise contact Service Zimmer GmbH |
| | | | Adjustment screw screwed-in in too deep | Screw out adjustement screw step by step |
| | | | Sliding block for floating mounting is blocked | Check screw length |
| | | | Height of clamping position not correct | Via "Selection guide" on the website, check whether the element matches the rail and check the alignment of the clamping position with the indicated clamping position on the housing |
| | | | DIR Signal changed before the specified movement time | Change the signal (DIR signal open/close) |
| LKE, LCE | Output status "Error" (Operating voltage) | Operating voltage exceeded/ undershot | Operating voltage is outside the permissible voltage range | Measure the operating voltage and correct for the permissible voltage range |
| LKE, LCE | Output status "Error" (Temperature) | Temperature range exceeded/ undershot | Heat dissipation not ensured | Ensure adequate ventilation |
| | | | Ambient temperature undershoots/exceeds the permissible operating temperature | Keep operating temperature according to technical data |